



August 21, 2015

Camas Washougal Fire Department
616 NE 4th Avenue
Camas, WA 98607

Statement of Exception
NFPA 1901 Standard for Automotive Fire Apparatus 2009 Edition

The crosslay design will not be compliant to NFPA section 16.7.5 Each discharge outlet shall be equipped with a valve that can be opened and closed smoothly at the flows shown in table 16.7.1 at pump discharge gauge pressures of 250 psi.

You have requested that there is a discharge outlet under the crosslays, one each side, controlled by one valve for both discharges on the pump panel.

Upon signing below, the fire department acknowledges that it has received this Statement Exception to NFPA 1901 and accepts responsibility.

Printed name and title, Fire Department Representative

Signature, Fire Department Representative

Date

